

FLUKE®

Hart Scientific

9133

Infrared Thermometer Calibrator
User's Guide

Rev. 531701

Fluke Hart Scientific • 799 E. Utah Valley Drive • American Fork, UT 84003-9775 • USA
Phone: +1.801.763.1600 • Telefax: +1.801.763.1010 • E-mail: support@hartscientific.com

www.hartscientific.com

Subject to change without notice. • Copyright © 2002 • Printed in USA

Table of Contents

1	Before You Start	1
1.1	Symbols Used	1
1.2	Safety Information	2
1.2.1	Warnings	2
1.2.2	Cautions	3
1.3	Hart Scientific Authorized Service Centers	4
2	Introduction	7
3	Specifications and Environment Conditions	9
3.1	Specifications	9
3.2	Environmental Conditions	10
3.3	Warranty	10
4	Quick Start	13
4.1	Unpacking	13
4.2	Set Up	13
4.3	Power	13
4.4	Setting the Temperature	14
5	Parts and Controls	15
5.1	Back Panel	15
5.2	Front Panel	16
6	General Operation	17
6.1	Changing Display Units	17
6.2	Switching to 230 V Operation	17
6.3	Ice Buildup/Purge	17
7	Controller Operation	19
7.1	Target Temperature	19
7.2	Temperature Set-point	19
7.2.1	Programmable Set-points	19
7.2.2	Set-point Value	21
7.3	Temperature Scale Units	21
7.4	Scan	22

7.4.1	Scan Control	22
7.4.2	Scan Rate.	22
7.5	Set-point Resistance	23
7.6	Temperature Scale Units	23
7.7	Secondary Menu	23
7.8	Heater Power.	23
7.9	Proportional Band	24
7.10	Controller Configuration	25
7.11	Operating Parameters	25
7.12	Serial Interface Parameters.	26
7.12.1	Baud Rate	26
7.12.2	Sample Period	26
7.12.3	Duplex Mode	27
7.12.4	Linefeed	27
7.13	Calibration Parameters	27
7.13.1	RO	28
7.13.2	ALPHA	28
7.13.3	DELTA	28
7.13.4	BETA	28
8	Digital Communication Interface	29
8.1	Serial Communications	29
8.1.1	Wiring	29
8.1.2	Setup	29
8.1.2.1	Baud Rate	30
8.1.2.2	Sample Period	30
8.1.2.3	Duplex Mode.	30
8.1.2.4	Linefeed	30
8.1.3	Serial Operation	31
8.2	Interface Commands	31
9	Calibration Procedure	35
9.1	Calibration Points.	35
9.2	Calibration Procedure	35
9.2.1	Compute DELTA	36
9.2.2	Compute RO and ALPHA	36
9.2.3	Compute BETA	37
9.2.4	Accuracy and Repeatability	37
10	Maintenance	39
11	Troubleshooting	41
11.1	Troubleshooting Problems, Possible Causes, and Solutions.	41
11.2	Comments	43

11.2.1	EMC Directive	43
11.2.2	Low Voltage Directive (Safety)	43

Figures

Figure 1 Temperature Gradient Between Probe and IR Target
Surface at Ambient of 30°C 10

Figure 2 Back Panel 15

Figure 3 Front Panel 16

Figure 4 Controller Operation Flow Chart 20

Figure 5 Serial Cable Wiring 29

Tables














Table 1	International Electrical Symbols	1
Table 2	Controller Communications Commands	32
Table 2	Controller Communications Commands continued	33




1 Before You Start

1.1 Symbols Used

Table 1 lists the International Electrical Symbols. Some or all of these symbols may be used on the instrument or in this manual.

Table 1 International Electrical Symbols

Symbol	Description
	AC (Alternating Current)
	AC-DC
	Battery
	CE Complies with European Union Directives
	DC
	Double Insulated
	Electric Shock
	Fuse
	PE Ground
	Hot Surface (Burn Hazard)
	Read the User's Manual (Important Information)
	Off
	On

Symbol	Description
	Canadian Standards Association
CAT II	OVERVOLTAGE (Installation) CATEGORY II, Pollution Degree 2 per IEC1010-1 refers to the level of Impulse Withstand Voltage protection provided. Equipment of OVERVOLTAGE CATEGORY II is energy-consuming equipment to be supplied from the fixed installation. Examples include household, office, and laboratory appliances.
	C-TIC Australian EMC Mark
	The European Waste Electrical and Electronic Equipment (WEEE) Directive (2002/96/EC) mark.

1.2 Safety Information

Use this instrument only as specified in this manual. Otherwise, the protection provided by the instrument may be impaired.

The following definitions apply to the terms “Warning” and “Caution”.

- “Warning” identifies conditions and actions that may pose hazards to the user.
- “Caution” identifies conditions and actions that may damage the instrument being used.

1.2.1

Warnings

To avoid personal injury, follow these guidelines.

- **BURN HAZARD – DO NOT** touch the IR target surface of the unit.
- The temperature of the IR target surface is the same as the actual temperature shown on the display. If the unit is set at 150°C and the display reads 150°C, the target surface is at 150°C.
- Temperatures above 70°C (158°F) are considered hazardous. Use extreme care when working with these temperatures. Observe all warnings and cautions given in this manual.
- The sheet metal of the instrument may exhibit extreme temperatures for areas close to the IR target surface.
- **DO NOT** turn off the unit at temperatures higher than 100°C. This could create a hazardous situation. Select a set-point less than 100°C and allow the unit to cool before turning it off.
- **DO NOT** operate this unit without a properly grounded, properly polarized power cord.
- **DO NOT** connect this unit to a non-grounded, non-polarized outlet.

- **HIGH VOLTAGE** is used in the operation of this equipment. **SEVERE INJURY OR DEATH** may result if personnel fail to observe safety precautions. Before working inside the equipment, turn the power off and disconnect the power cord.
- Always replace the fuse with one of the same rating, voltage, and type.
- Allow at least six inches of space between the instrument and nearby objects. **DO NOT** place instrument under a flammable structure.
- **DO NOT** use this unit for any application other than calibration work.
- **DO NOT** use this unit in environments other than those listed in the user's guide.
- **DO NOT** operate near flammable materials.
- Use of this instrument at **HIGH TEMPERATURES** for extended periods of time requires caution.
- Completely unattended high temperature operation is not recommended for safety reasons.
- Before initial use, after transport, and anytime the instrument has not been energized for more than 10 days, the calibrator must be energized for a dry-out period of 1 to 2 hours before it can be assumed to meet all of the safety requirements of the IEC 1010-1.
- The instrument can generate extreme temperatures. Precautions must be taken to prevent personal injury or damage to objects.
- Use only a grounded AC mains supply of the appropriate voltage to power the instrument. Refer to Section 3.1, Specifications for power details.
- The instrument is equipped with operator accessible system fuses. If a fuse blows, it may be due to a power surge or failure of a component. Replace the fuse once. If the fuse blows a second time, it is likely caused by failure of a component part. If this occurs, contact an Authorized Fluke Hart Scientific Service Center (see Section 1.3). Always replace the fuse with one of the same rating, voltage, and type. Never replace the fuse with one of a higher current rating.
- This instrument is intended for indoor operation only.
- Follow all safety guidelines listed in the user's manual.
- Calibration Equipment should only be used by Trained Personnel.

1.2.2



Cautions

- Use the target cover at temperatures below 5°C. If ice forms on the target, the IR probe will not indicate the correct temperature.
- **DO NOT** use fluids to clean out the target surface.

- **DO NOT** change the values of the calibration constants from the factory set values. The correct setting of these parameters is important to the safety and proper operation of the calibrator.
- **DO** use a ground fault interrupt device.
- Operate the instrument in room temperatures between 5–50°C (41–122° F). Allow sufficient air circulation by leaving at least 6 inches of space between the instrument and nearby objects.
- The instrument is a precision instrument. Although it has been designed for optimum durability and trouble free operation, it must be handled with care. The convenient fold-up handle allows one hand carrying. The instrument should not be operated in excessively wet, oily, dusty, or dirty environments. It is important to keep the calibration probe well and the IR target surface clean and clear of any foreign matter. Do not operate near flammable materials.
- **DO NOT** use fluids to clean out the calibration probe well or on the IR target surface.
- Before initial use, after transport, and anytime the instrument has not been energized for a “dry-out” period of 1-2 hours before it can be assumed to meet all of the safety requirements of the IEC 1010-1.
- If a main supply power fluctuation occurs, immediately turn off the instrument. Wait until the power has stabilized before re-energizing the instrument.

1.3 Fluke Hart Scientific Authorized Service Centers

Please contact one of the following authorized Service Centers to coordinate service on your Hart product:

Fluke Hart Scientific

799 E. Utah Valley Drive
American Fork, UT 84003-9775
USA

Phone: +1.801.763.1600
Telefax: +1.801.763.1010
E-mail: support@hartscientific.com

Fluke Nederland B.V.

Customer Support Services
Science Park Eindhoven 5108
5692 EC Son

NETHERLANDS

Phone: +31-402-675300

Telefax: +31-402-675321

E-mail: ServiceDesk@fluke.nl

Fluke Int'l Corporation

Service Center - Instrimpex

Room 2301 Sciteck Tower

22 Jianguomenwai Dajie

Chao Yang District

Beijing 100004, PRC

CHINA

Phone: +86-10-6-512-3436

Telefax: +86-10-6-512-3437

E-mail: xingye.han@fluke.com.cn

Fluke South East Asia Pte Ltd.

Fluke ASEAN Regional Office

Service Center

60 Alexandra Terrace #03-16

The Comtech (Lobby D)

118502

SINGAPORE

Phone: +65 6799-5588

Telefax: +65 6799-5588

E-mail: antng@singa.fluke.com

When contacting these Service Centers for support, please have the following information available:

- model number
- serial number
- voltage
- complete description of the problem

2 Introduction

The Fluke Hart Scientific 9133 Mid-Range Field IR Calibrator may be used as a portable instrument or bench top temperature calibrator for calibrating point IR thermometers. The 9133 is small enough to use in the field, and accurate enough to use in the lab. Calibrations may be done over a range of -30°C to 150°C (-22°F to 302°F). Temperature display and setability resolution of the 9133 is 0.1 degrees.

The instrument features:

- Rapid heating and cooling
- RS-232 interface capability

Built in programmable features include:

- Temperature scan rate control
- Eight set-point memory
- Adjustable readout in $^{\circ}\text{C}$ or $^{\circ}\text{F}$

The temperature is accurately controlled by Hart's digital controller. The controller uses a precision platinum RTD as a sensor and controls the well temperature with a FET driven thermal electric device.

For improved uncertainties, a 0.125" diameter external reference thermometer may be used in the calibration probe hole at the top of the instrument. When using an external reference thermometer, the instrument accuracy, stability, and ambient temperature effects on the surface can be minimized.

The LED front panel continuously shows the current temperature. The temperature may be easily set with the control buttons to any desired temperature within the specified range. The instrument's multiple fault protection devices insure user and instrument safety and protection.

The 9133 calibrator was designed for portability, low cost, and ease of operation. Through proper use, the instrument will provide continued accurate calibration of temperature sensors and devices. The user should be familiar with the safety guidelines and operating procedures of the calibrator as described in this user guide.

3 Specifications and Environment Conditions

3.1 Specifications

Temperature Range[†]	-30°C to 150°C (-22°F to 302°F)
Accuracy[‡]	±0.4°C (±0.72°F) [using 1/8" PRT]
Stability	±0.1°C (±0.18°F)
Target Size	2.25" (57 mm)
Target Emissivity	0.95 (±0.02 from 8 to 14μM)
Resolution	0.1° C or F
Heating Time	15 minutes (25°C to 150°C)
Cooling Time	15 minutes (25°C to -20°C)
Power	115 VAC (±10%), 1.5 A, or 230 VAC (±10%), 1.0 A, switchable, 50/60 Hz
Size (H,W,D)	152 x 286 x 267 mm (6 x 11.25 x 10.5")
Weight	4.6 kg (10 lb.)
Safety	OVERVOLTAGE (Installation) CATEGORY II, Pollution Degree 2 per IEC1010-1

[†]When using a purge, the high and low range are reduced. This amount depends on the flow and temperature of the purge.

[‡]Temperature difference between the IR target surface and the reference probe are calculated as shown in the graph in Figure 1 on page 10. **Note:** As the temperature of the IR target surface increases, the temperature difference decreases.




Figure 1 Temperature Gradient Between Probe and IR Target Surface at Ambient of 30°C

3.2 Environmental Conditions

Although the instrument has been designed for optimum durability and trouble-free operation, it must be handled with care. The instrument should not be operated in an excessively dusty or dirty environment. Maintenance and cleaning recommendations can be found in the Maintenance section of this manual.

The instrument operates safely under the following conditions:

- temperature range: 5–50°C (41–122°F)
- ambient relative humidity: maximum 80% for temperature <31°C, decreasing linearly to 50% at 40°C
- pressure: 75kPa–106kPa
- mains voltage within $\pm 10\%$ of nominal
- vibrations in the calibration environment should be minimized
- altitudes less than 2,000 meters

3.3 Warranty

Fluke Hart Scientific (Hart) warrants this product to be free from defects in material and workmanship under normal use and service for a period as stated in our current product catalog from the date of shipment. This war-

warranty extends only to the original purchaser and shall not apply to any product which, in Hart's sole opinion, has been subject to misuse, alteration, abuse or abnormal conditions of operation or handling.

Software is warranted to operate in accordance with its programmed instructions on appropriate Hart products. It is not warranted to be error free.

Hart's obligation under this warranty is limited to repair or replacement of a product which is returned to Hart within the warranty period and is determined, upon examination by Hart, to be defective. If Hart determines that the defect or malfunction has been caused by misuse, alteration, abuse or abnormal conditions of operation or handling, Hart will repair the product and bill the purchaser for the reasonable cost of repair.

To exercise this warranty, the purchaser must forward the product after calling or writing Hart for authorization. Hart assumes NO risk for in-transit damage.

For service or assistance, please contact an Authorized Fluke Hart Scientific Service Center (see Section 1.3).

THE FOREGOING WARRANTY IS PURCHASER'S SOLE AND EXCLUSIVE REMEDY AND IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTY OR MERCHANTABILITY, OR FITNESS FOR ANY PARTICULAR PURPOSE OR USE. FLUKE HART SCIENTIFIC SHALL NOT BE LIABLE FOR ANY SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES OR LOSS WHETHER IN CONTRACT, TORT, OR OTHERWISE.

4 Quick Start

4.1 Unpacking

Unpack the calibrator carefully and inspect it for any damage that may have occurred during shipment. If there is shipping damage, notify the carrier immediately.

Verify that the following components are present:

- 9133 calibrator
- report of calibration
- power cord
- user's guide
- serial cable
- target cover
- 9930 software

4.2 Set Up

Place the calibrator on a flat surface with at least 6 inches of free space around the instrument. The prop may be swung down to raise the front of the instrument from a horizontal position. Plug the power cord into a grounded mains outlet. Observe that the nominal voltage corresponds to that indicated on the back of the calibrator.

Turn on the power to the calibrator by toggling the power switch on. The fan should begin quietly blowing air through the instrument and the controller display should illuminate after 3 seconds. After a brief self-test the controller should begin normal operation. If the unit fails to operate please check the power connection.

The thermal electric devices will start operating to bring the temperature of the calibrator to the set-point temperature and the display will begin to show the actual target temperature.



Caution: Use the target cover at temperatures below 5°C. If ice forms on the target, the IR probe will not indicate the correct temperature.

4.3 Power

Plug the instrument power cord into a mains outlet of the proper voltage, frequency, and current capability. Refer to Section 3.1, Specifications for power details. Turn the instrument on using the rear panel "POWER" switch. The instrument turns on and begins to heat to the previously pro-

grammed temperature set-point. The front panel LED display indicates the actual instrument temperature.

4.4 Setting the Temperature

Section 8.2 explains in detail how to set the temperature set-point on the calibrator using the front panel keys. The procedure is summarized here.

1. Press the "SET" button twice to access the set-point value.
2. Press the "UP" or "DOWN" button to change the set-point value.
3. Press the "SET" button to program in the new set-point.
4. Press the "EXIT" button to return to the temperature display.

When the set-point temperature is changed the controller switches the heater on or off to raise or lower the temperature. The displayed temperature gradually changes until it reaches the set-point temperature. The target may require 5 to 10 minutes to reach the set-point depending on the span. Another 5 to 10 minutes is required to stabilize within $\pm 0.1^{\circ}\text{C}$ of the set-point. Ultimate stability may take 15 to 20 minutes more of stabilization time.

5 Parts and Controls

5.1 Back Panel

The back panel (Figure 2) consists of the power inlet, power switch, serial port, and fan.




Figure 2 Back Panel

Power Inlet – At the rear of the calibrator is the removable power cord in let that plugs into an IEC grounded socket.

Power Switch – The power switch is located on the power entry module (PEM). The PEM also houses the fuses. The PEM allows the unit to be field switchable for 115 VAC ($\pm 10\%$) or 230 VAC ($\pm 10\%$) operation. (See Section 6.2, Switching to 230 V Operation.)

Serial Port – A DB-9 male connector is present for interfacing the calibrator to a computer or terminal with serial RS-232 communications.

Fan – The fan inside the calibrator varies in speed. As the target temperature increases the fan speed decreases. Slots are provided for airflow. The area around the calibrator must be kept clear to allow adequate ventilation. The airflow is directed out the two sides.

5.2 Front Panel

The front panel (Figure 3) consists of the controller display, controller key-pad, and target assembly.



Figure 3 Front Panel

Controller Display – The digital display displays set and actual temperatures and various calibrator functions, settings, and constants. The display shows temperatures in units according to the selected scale °C or °F.

Controller Keypad – The four button keypad allows easy setting of the set-point temperature. The control buttons (SET, DOWN, UP, and EXIT) are used to set the calibrator temperature set-point, access and set other operating parameters, and access and set calibration parameters.

Setting the control temperature is done directly in degrees of the current scale. The control temperature can be set to one-tenth of a degree Celsius or Fahrenheit.

The functions of the buttons are as follows:

SET – Used to display the next parameter in a menu and to set parameters to the displayed value.

DOWN – Used to decrement the displayed value of parameters.

UP – Used to increment the displayed value.

EXIT – Used to exit from a menu. When the EXIT button is pressed any changes made to the displayed value are ignored.

Target Assembly – The target assembly is 2.25" (57 mm) in diameter and has an emissive of 0.95.

6 General Operation

6.1 Changing Display Units

The 9133 can display temperature in Celsius or Fahrenheit. The temperature units are shipped from the factory set to Celsius. There are two ways to change to Fahrenheit or back to Celsius as described below.

1. Press the "SET" and "UP" buttons simultaneously. The units are changed.

Or

1. Press the "SET" button three times from the temperature display to show Un =C
2. Press the "UP" or "DOWN" button to change units.

6.2 Switching to 230 V Operation

The 9133 is switchable from 115 VAC to 230 VAC 50/60 Hz. To change from 115 VAC to 230 VAC follow the steps below.

1. Unplug the instrument.
2. With a small straight slot screwdriver remove the fuse holder located on the rear panel.
3. Replace the two 3 A 250 V fuses with two 1.6 AT 250 V fuses.
4. Replace the fuse holder with the "~" in the display window.

Note: If "~" is not displayed in the window, the unit will not heat or cool.

6.3 Ice Buildup/Purge

To prevent ice buildup on the target at temperatures below 5°C, use the target cover and/or a dry gas purge. When taking measurements using the target cover, place the target cover in place and set the set-point temperature to the desired temperature, remove the target cover, take a sample, and replace the cover. When ice forms on the target, change the unit set-point higher than 5°C to melt the excess ice. When the ice melts pat the excess water off with a clean dry cloth. **Do not wipe the front plate.** If a clean dry cloth is not available, change the set-point to 100°C or higher, to evaporate the excess water.

When using a dry gas purge, the instrument will not reach minimum temperature. An example of a gas purge is dry nitrogen connected through a 1/8" inner diameter tube to the purge fitting located at the front bottom of the target. The nitrogen gas is controlled to fill the chamber in front of the

target at a rate that will not allow airflow to affect the target. **Note:** If the gas contains any moisture, ice will form on the target.

7 Controller Operation

This section discusses in detail how to operate the instrument temperature controller using the front control panel. By using the front panel key-switches and LED display, the user may monitor the target temperature, adjust the set-point temperature in degrees C or F, monitor the output power, adjust the controller proportional band, and program the operating parameters, program parameters, serial interface configuration, and the controller calibration parameters. Operation of the functions and parameters is shown in the flowchart in Figure 4 on page 20. This chart may be copied for reference.

In the following discussion a button with the word "SET", "UP", "DOWN", or "EXIT" inside indicates the panel button while the dotted box indicates the display reading. Explanation of the button or display reading is to the right of each button or display value.

7.1 Target Temperature

The digital LED display on the front panel allows direct viewing of the actual temperature. This temperature value is what is normally shown on the display. The units C or F, of the temperature value are displayed at the right. For example,

 *Target temperature in degrees Celsius*

The temperature display function may be accessed from any other function by pressing the "EXIT" button.

7.2 Temperature Set-point

The temperature set-point can be set to any value within the range and resolution as given in the specifications.

Setting the temperature involves selecting one of the eight set-points in memory and then adjusting the set-point value.

7.2.1 Programmable Set-points

The controller stores eight (8) set-point temperatures in memory. The set-points can be quickly recalled to conveniently set the instrument to a previously programmed temperature set-point.

To set the temperature, first select the set-point memory. This function is accessed from the temperature display function by pressing the "SET" button. The number of the set-point memory currently being used is shown at the left on the display followed by the current set-point value.






Figure 4 Controller Operation Flow Chart

 Well temperature in degrees Celsius

 Access set-point memory

 Set-point memory 1, 100°C currently used

To change the set-point memory to another preset value press the “UP” or “DOWN” button.

 New set-point memory 4, 150°C

Press the “SET” button to display the new selection and access the set-point value.

 Accept selected set-point memory

7.2.2 Set-point Value

The set-point value may be adjusted after selecting the set-point memory and pressing the “SET” button. The set-point value is displayed with the units, C or F, at the left.


 Set-point value 4, 120.0°C

If the set-point value does not need to be changed, press the “EXIT” button to resume displaying the instrument temperature. Press the “UP” or the “DOWN” button to adjust the set-point value.

 Increment display

 New set-point value

When the desired set-point value is reached press the “SET” button to accept the new value. If the “EXIT” button is pressed, any changes made to the set-point are ignored.

 Accept new set-point value

7.3 Temperature Scale Units

The temperature scale units of the controller can be set by the user to degrees Celsius (°C) or Fahrenheit (°F). The units are used in displaying the well temperature, set-point, and proportional band.

Press the “SET” button after adjusting the set-point value to change display units

$U_n = C$ *Scale units currently selected*

Press the "UP" or "DOWN" button to change the units.

 *Change units*

$U_n = F$ *New units selected*

Press the "SET" button to accept the new selection and resume displaying the display temperature.

7.4 Scan

The scan rate can be set and enabled so that when the set-point is changed the instrument heats or cools at a specified rate, in degrees C per minute only, until it reaches the new set-point. With the scan disabled the instrument heats or cools at the maximum possible rate.

7.4.1 Scan Control

The scan is controlled with the scan on/off function that appears in the main menu after the temperature scale units.

$S_c = OFF$ *Scan function off*

Press the "UP" or "DOWN" button to toggle the scan on or off.

$S_c = ON$ *Scan function on*

Press the "SET" button to accept the present setting and to continue.

 *Accept scan setting*

7.4.2 Scan Rate

The next function in the main menu is the scan rate. The scan rate can be set from .1 to 99.9°C/min. The maximum scan rate however is actually limited by the natural heating or cooling rate of the instrument.

The scan rate function appears in the main menu after the scan control function. The scan rate units are in degrees Celsius per minute.

$S_r = 10.0$ *Scan rate in C/min*

Press the "UP" or "DOWN" button to change the scan rate.

$S_r = 2.0$ *New scan rate*

Press the "SET" button to accept the new scan rate and continue.



Accept scan rate

7.5 Set-point Resistance

To display the Set-point Resistance, press the "SET" and "DOWN" buttons simultaneously when the temperature is displayed. When the "SET" and "DOWN" buttons are released the temperature is again displayed. This value is used to calibrate the unit and is not adjustable.

7.6 Temperature Scale Units

To toggle between °C and °F, press the "SET" and "UP" keys simultaneously when the temperature is displayed.


7.7 Secondary Menu

Functions used less often are accessed within the secondary menu. Press and hold the "SET" and EXIT buttons to access the secondary menu. The first function in the secondary menu is the heater power display. (See Figure 4 on page 20.)

7.8 Heater Power

The temperature controller controls the temperature of the well by pulsing the heater on and off. The total power being applied to the heater is determined by the duty cycle or the ratio of heater on time to the pulse cycle time. By knowing the amount of heating the user can tell if the instrument is heating "UP" to the set-point, cooling "DOWN", or controlling at a constant temperature. Monitoring the percent heater power lets the user know the stability of the well temperature. With good control stability the percent heating power should not fluctuate more than $\pm 1\%$ within one minute.

The heater power display is accessed in the secondary menu. Press and hold the "SET" and "EXIT" buttons. The heater power is displayed as a percentage of full power.



Target temperature



Access heater power in percent



Flashes 5 E C for secondary menu and then displays the heater power

 *Heater power in percent*

To exit out of the secondary menu press and hold the "EXIT" button. To continue on to the proportional band setting function, press the "SET" button.



7.9 Proportional Band


In a proportional controller such as this, the heater output power is proportional to the target temperature over a limited range of temperatures around the set-point. This range of temperature is called proportional band. At the bottom of the proportional band, the heater output is 100%. At the top of the proportional band, the heater output is 0. Thus as the temperature rises the heater power is reduced. In this way the temperature is maintained at a fairly constant level.

The temperature stability of the instrument depends on the width of the proportional band. If the band is too wide, the target temperature deviates excessively from the set-point due to varying external conditions. This deviation is caused by the power output changing very little with temperature and the controller not responding well to changing conditions or noise in the system. If the proportional band is too narrow the temperature may swing back and forth because the controller overreacts to temperature variations. For best stability control, the proportional band must be set for the optimum width by the user in any given application.


The optimum proportional band width is set at the factory to about 25.0°C. The user may alter the proportional band width to optimize the control characteristics for a particular application. However, we recommend the proportional band be changed only by knowledgeable personnel.


The proportional band width is easily adjusted from the front panel. The width may be set to discrete values in degrees C or F depending on the selected units. The proportional band adjustment can be accessed within the secondary menu. Press the "SET" and "EXIT" buttons to enter the secondary menu and show the heater power. Then press the "SET" button to access the proportional band.

 +  *Access heater power in secondary menu*

 *Flashes 5EC for secondary menu and then displays the heater power*

 *Heater power in percent*

 *Access proportional band*

 *Flashes PR0P for proportional band and then displays the proportional band setting*

4.1 *Proportional band setting*

To change the proportional band setting press the “UP” or “DOWN” buttons.

UP *Increment display*

10. *New proportional band setting*

To store the new setting press the “SET” button. Press the “EXIT” button to continue without storing the new value.

SET *Accept the new proportional band setting*

7.10 Controller Configuration

The controller has a number of configuration, operation, and calibration parameters that are programmable via the front panel. These are accessed from the secondary menu after the proportional band by pressing the “SET” button. There are three sets of configuration parameters – operating parameters, serial interface parameters, and calibration parameters. The menus are selected by using the “UP” and “DOWN” buttons and then pressing the “SET” button.

7.11 Operating Parameters

The operating parameters menu contains the High Limit parameter. The operating parameter menu is indicated by,

P A r *Operating parameters menu*

The High Limit parameter adjusts the upper set-point temperature limit. The factory default and maximum are set to 160°C. For safety, a user can adjust the High Limit parameter down so the maximum temperature set-point is restricted. Press the “SET” button to enable adjustment of the High Limit parameter.

HL *Flashes HL and then displays the setting*

H = 125 *Current HL setting*

To change to High Limit setting, use the “UP” or “DOWN” button.

H = 90 *New High Limit setting*

Press the “SET” button to save this setting.

7.12 Serial Interface Parameters

The serial interface parameters menu contains parameters, which determine the operation of the serial interface. The parameters in the menu are – baud rate, sample period, duplex mode, and linefeed. The serial RS-232 interface parameters menu is indicated by,

S E R I A L

Serial RS-232 interface parameters menu

Press the “UP” button from the operations Parameters Menu to access the Serial menu. Press “SET” to enter the menu.

7.12.1 Baud Rate

The baud rate is the first parameter in the menu. The baud rate setting determines the serial communications transmission rate. The baud rate of the serial communications may be programmed to 300, 600, 1200, 2400, 4800, or 9600. The default setting is 2400 baud.

b A U D

Flashes b A U D and then displays the setting

2400 b

Current baud rate

Use the “UP” or “DOWN” buttons to change the baud rate setting.

4800 b

New baud rate

Press the “SET” button to store the new setting as the baud rate or press the “EXIT” button to skip to the next parameter without storing the new setting.

7.12.2 Sample Period

The sample period is the next parameter in the serial interface parameters menu. The sample period is the time period in seconds between temperature measurements transmitted from the serial interface. If the sample rate is set to 5, the instrument transmits the current measurement over the serial interface approximately every five seconds. The automatic sampling is disabled with a sample period of 0.

S P E R

Flashes S P E R and then displays the setting

S P = 1

Current sample period (seconds)

Use the “UP” or “DOWN” buttons to adjust the setting.

S P = 50

New sample period

Press the "SET" button to store the new setting as the sample period or press the "EXIT" button to skip to the next parameter without storing the new setting.

7.12.3 Duplex Mode

The next parameter is the duplex mode. The duplex mode may be set to full duplex or half duplex. With full duplex any commands received by the instrument via the serial interface are immediately echoed or transmitted back to the device of origin. With half duplex the commands are executed but not echoed.

`d u P L`

Flashes d u P L and then displays the setting

`d = F U L L`

Current duplex mode

Use the "UP" or "DOWN" buttons to adjust the setting.

`d = H A L F`

New duplex mode setting

Press the "SET" button to store the new setting as the duplex mode or press the "EXIT" button to skip to the next parameter without storing the new setting.

7.12.4 Linefeed

The final parameter in the serial interface menu is the linefeed mode. This parameter enables (on) or disables (off) transmission of a linefeed character (LF, ASCII 10) after transmission of any carriage-return.

`L F`

Flashes L F and then displays the setting

`L F = O n`

Current linefeed setting

Use the "UP" or "DOWN" buttons to adjust the setting.

`L F = O F F`

New linefeed setting

Press the "SET" button to store the new setting as the linefeed or press the "EXIT" button to skip to the next parameter without storing the new setting.

7.13 Calibration Parameters

The probe parameters menu contains the parameters, RO, ALPHA, DELTA, and BETA, which characterize the resistance-temperature relationship of the platinum control probe. These values are set at the factory and must not

be altered. The correct values are important to the accuracy and proper and safe operation of the instrument. Access to these parameters is available to the user so that in the event that the controller memory fails the user may restore these values to the factory settings. The user should have a list of these constants on the Report of Calibration that ships with the instrument.



Caution: *DO NOT change the value of the instrument calibration constants from the factory set values. The correct setting of these parameters is important to the safety and proper operation of the unit.*

The calibration parameters menu is indicated by,

 *calibration parameters menu*

Press the "SET" button five times to enter the menu. The name of the parameter flashes on the display and then the value is displayed. The value of the parameter may be changed using the "UP" and "DOWN" buttons. After the desired value is reached press the "SET" button to set the parameter to the new value. Pressing the "EXIT" button causes the parameter to be skipped ignoring any changes that may have been made.

7.13.1 RO

This probe parameter refers to the resistance of the control probe at 0°C. The value of this parameter is set at the factory for best instrument accuracy.

7.13.2 ALPHA

This probe parameter refers to the average sensitivity of the probe between 0 and 100°C. The value of this parameter is set at the factory for best instrument accuracy.

7.13.3 DELTA

This probe parameter refers to the curvature of the resistance-temperature relationship or the sensor. The value of this parameter is set at the factory for best instrument accuracy.

7.13.4 BETA

This probe parameter characterizes the low temperatures. The value of this parameter is set at the factory for best instrument accuracy.

8 Digital Communication Interface

The 9133 calibrator is capable of communicating with and being controlled by other equipment through the digital interface. With a digital interface the instrument may be connected to a computer or other equipment. This allows the user to set the instrument temperature, monitor the temperature, and access any of the other controller functions, all using remote communications equipment. Communications commands are summarized in Table 2 on page 32.

8.1 Serial Communications

The RS-232 serial interface allows serial digital communications over fairly long distances (15.24 meters). With the serial interface the user may access any of the functions, parameters and settings discussed in Section 7, Controller Operation with the exception of the baud rate setting. The serial interface operates with eight data bits, one stop bit, and no parity.

8.1.1 Wiring

The serial communications cable attaches to the instrument through the DB-9 connector at the back of the instrument. Figure 5 shows the pin-out of this connector and suggested cable wiring. To eliminate noise, the serial cable should be shielded with low resistance between the connector (DB-9) and the shield.

8.1.2 Setup

Before operation, the serial interface of the instrument must be set up by programming the baud rate and other configuration parameters. These parameters are programmed within the serial interface menu. The serial interface parameters menu is outlined in Section 7.12.

To enter the serial parameter programming mode first, press

RS-232 Cable Wiring for IBM PC and Compatibles




Figure 5 Serial Cable Wiring

the "EXIT" button while pressing the "SET" button and release to enter the secondary menu. Press the "SET" button repeatedly until the display reads "P r o b E". This is the menu selection. Press the "UP" button repeatedly until the serial interface menu is indicated with "S E R I A L". Finally press the "SET" button to enter the serial parameter menu. The serial interface parameter menu contains the BAUD rate, the sample rate, the duplex mode, and the linefeed parameter.

8.1.2.1 Baud Rate

The baud rate is the first parameter in the menu. The display prompts with the baud rate parameter by showing "b A U d". Press the "SET" button to choose to set the baud rate. The current baud rate value is displayed. The baud rate of the instrument may be programmed to 300, 600, 1200, or 2400 baud. The baud rate is pre-programmed to 2400 baud. Use "UP" or "DOWN" to change the baud rate value. Press the "SET" button to set the baud to the new value or the "EXIT" button to abort the operation and skip to the next parameter in the menu.

8.1.2.2 Sample Period

The sample period is the next parameter in the menu and prompted with "S A M P L E". The sample period is the time period, in seconds, between temperature measurements transmitted from the serial interface. If the sample rate is set to 5, the instrument transmits the current measurement over the serial interface approximately every five seconds. The automatic sampling is disabled with a sample period of 0. Press the "SET" button to choose to set the sample period. Adjust the period with the "UP" or "DOWN" button and then use the "SET" to set the sample rate to the displayed value.

8.1.2.3 Duplex Mode

The next parameter is the duplex mode indicated with "d U P L". The duplex mode may be set to half duplex ("H A L F") or full duplex ("F U L L"). With full duplex any commands received by the instrument via the serial interface are immediately echoed or transmitted back to the device of origin. With half duplex the commands are executed but not echoed. The default setting is full duplex. The mode may be changed using "UP" or "DOWN" and pressing "SET".

8.1.2.4 Linefeed

The final parameter in the serial interface menu is the linefeed mode. This parameter enables ("O n") or disables ("O F F") transmission of a linefeed character (LF, ASCII 10) after transmission of any carriage-return. The default setting is with linefeed on. The mode may be changed using "UP" or "DOWN" and pressing "SET".

8.1.3 Serial Operation

Once the cable has been attached and the interface set up properly the controller immediately begins transmitting temperature readings at the programmed rate. The set-point and other commands may be sent to the instrument via the serial interface to set the instrument and view or program the various parameters. The interface commands are discussed in Section 8.2, Interface Commands.

8.2 Interface Commands

The various commands for accessing the instrument controller functions via the digital interfaces are listed in Table 2. These commands are used with both the RS-232 serial interface and the IEEE-488 GPIB interface. In either case the commands are terminated with a carriage-return character. The interface makes no distinction between upper and lower case letters, hence either may be used. Commands may be abbreviated to the minimum number of letters, which determines a unique command. A command may be used to either set a parameter or display a parameter depending on whether or not a value is sent with the command following a "=" character. For example, an "s"<cr> returns the current set-point and an "s=50.00"<cr> sets the set-point to 50.00 degrees.

In the following list of commands, characters or data within brackets, "[" and "]", are optional. A slash, "/", denotes alternate characters or data. Numeric data, denoted by "n", may be entered in decimal or exponential notation. Characters are shown in lower case although upper case may be used. Spaces may be added within command strings and are simply ignored. Backspace (BS, ASCII 8) may be used to erase the previous character. A terminating CR is implied with all commands.

Table 2 Controller Communications Commands

Command Description	Command Format	Command Example	Returned	Returned Example	Acceptable Values
Display Temperature					
Read current set-point	s[etpoint]	s	set: 999.9 {C or F}	set: 100.00 C	
Set current set-point to <i>n</i>	s[etpoint]= <i>n</i>	s=200.0			Instrument Range
Read temperature	t[emperature]	t	t: 999.9 {C or F}	t: 55.6 C	
Read temperature units	u[nits]	u	u: x	u: C	
Set temperature units:	u[nits]=c/f				C or F
Set temperature units to Celsius	u[nits]=c	u=c			
Set temperature units to Fahrenheit	u[nits]=f	u=f			
Read scan mode	sc[an]	sc	scan: {ON or OFF}	scan:ON	
Set scan mode	sc[an]=on/off	sc=on			ON or OFF
Read scan rate	sr[ate]	sr	srat: 99.9 {C or F}/min	srat:12.4C/min	
Set scan rate	sr[ate]= <i>n</i>	sr=1.1			.1 to 99.9
Secondary Menu					
Read proportional band setting	pr[opband]	pr	pb: 999.9	pb: 15.9	
Set proportional band to <i>n</i>	pr[opband]= <i>n</i>	pr=8.83			Depends on Configuration
Read heater power (duty cycle)	po[wer]	po	po: 999.9	po: 1.0	
Configuration Menu					
Operating Parameters Menu					
Read high limit	hl	hl	hl:999	hl:126	
Set high limit	hl= <i>n</i>	hl=90			50–160
Serial Interface Menu					
Read serial sample setting	sa[mple]	sa	sa: 9	sa: 1	
Set serial sampling setting to <i>n</i> seconds	sa[mple]= <i>n</i>	sa=0			0 to 999
Set serial duplex mode:	du[plex]=f[ull]/h[alf]				FULL or HALF
Set serial duplex mode to full	du[plex]=f[ull]	du=f			
Set serial duplex mode to half	du[plex]=h[alf]	du=h			
Set serial linefeed mode:	lf[eed]=on/of[f]				ON or OFF

Controller Communications Commands continued

Command Description	Command Format	Command Example	Returned	Returned Example	Acceptable Values
Set serial linefeed mode to on	lf[eed]=on	lf=on			
Set serial linefeed mode to off	lf[eed]=of[f]	lf=of			
Calibration Menu					
Read RO calibration parameter	r[0]	r	r0: 999.999	r0: 100.578	
Set RO calibration parameter to <i>n</i>	r[0]=n	r=100.324			90 to 110
Read ALPHA calibration parameter	al[pha]	al	al: 9.9999999	al: 0.0038573	
Set ALPHA calibration parameter to <i>n</i>	al[pha]=n	al=0.0038433			.002 to .005
Read DELTA calibration parameter	de[lta]	de	de:9.99999	de: 1.507	
Set DELTA calibration parameter	de[lta]=n	de=1.3742			0–3.0
Read BETA calibration parameter	be[ta]	be	be:9.999	be:0.342	
Set BETA calibration parameter	be[ta]=n	be=0.342			–100.0 to 100.0
Functions not on menu					
Read firmware version number	*ver[sion]	*ver	ver.9999,9.99	ver.9133,1.00	
Read structure of all commands	h[elp]	h	list of commands		
Read all operating parameters	all	all	list of parameters		
Legend:	[] Optional Command data {} Returns either information n Numeric data supplied by user 9 Numeric data returned to user x Character data returned to user				
Note:	When DUPLEX is set to FULL and a command is sent to READ, the command is returned followed by a carriage return and linefeed. Then the value is returned as indicated in the RETURNED column.				

9 Calibration Procedure

Sometimes the user may want to calibrate the instrument to improve the temperature set-point accuracy. Calibration is done by adjusting the controller probe calibration constants RO, ALPHA, DELTA, and BETA so that the temperature of the calibrator as measured with a standard thermometer agrees more closely with the set-point. The thermometer used must be able to measure the well temperature with higher accuracy than the desired accuracy of the calibrator. By using a good thermometer and following this procedure the instrument can be calibrated to an accuracy of better than 0.5°C up to 150°C.

9.1 Calibration Points

In calibrating the instrument, RO, ALPHA, DELTA, and BETA, are adjusted to minimize the set-point error at each of three different temperatures. Any three appropriately separated temperatures may be used for the calibration. Improved results can be obtained for shorter ranges when using temperatures that are just within the most useful operating range of the instrument. The farther apart the calibration temperatures, the larger the calibrated range. However, the calibration error will also be greater over that range. If, for instance, -20°C to 100°C is chosen as the calibration range, the calibrator may achieve an accuracy of $\pm 0.3^\circ\text{C}$ over that range (-20 to 100°C). Choosing a range of 50°C to 90°C may allow the calibrator to have a better accuracy of maybe $\pm 0.2^\circ\text{C}$ over the narrower range but, outside that range, the accuracy may be only $\pm 1.5^\circ\text{C}$.

9.2 Calibration Procedure

1. Choose four set-points to use in the calibration of the RO, ALPHA, DELTA, and BETA parameters. These set-points are generally -25°C, 0°C, 60°C, and 125°C but other set-points may be used if desired or necessary.
2. Set the instrument to the low set-point. When the instrument reaches the set-point and the display is stable, wait 15 minutes or so and then take a reading. Sample the set-point resistance by holding down the "SET" key and pressing the "DOWN" key. Write these values down as T_1 and R_1 respectively.
3. Repeat step 2 for the other three set-points recording them as T_2 , R_2 , T_3 , R_3 , T_4 and R_4 respectively.
4. Using the recorded data, calculate new values for RO, ALPHA, DELTA, and BETA parameters using the equations given below.

9.2.1 Compute DELTA

$$A = T_4 - T_3$$

$$B = T_3 - T_2$$

$$C = \left[\frac{T_4}{100} \right] \left[1 - \frac{T_4}{100} \right] - \left[\frac{T_3}{100} \right] \left[1 - \frac{T_3}{100} \right]$$

$$D = \left[\frac{T_3}{100} \right] \left[1 - \frac{T_3}{100} \right] - \left[\frac{T_2}{100} \right] \left[1 - \frac{T_2}{100} \right]$$

$$E = R_4 - R_3$$

$$F = R_3 - R_2$$

$$\text{delta} = \frac{AF - BE}{DE - CF}$$

T_{1-4} - Measured temperature using the reference thermometer

R_{1-4} - Value of R from the 9133 display (Press SET and DOWN at the same time)

Where

T_1 and R_1 are the measured temperature and resistance at -25°C

T_2 and R_2 are the measured temperature and resistance at 0°C

T_3 and R_3 are the measured temperature and resistance at 60°C

T_4 and R_4 are the measured temperature and resistance at 125°C

9.2.2 Compute RO and ALPHA

$$a_1 = T_2 + \text{delta} \left[\frac{T_2}{100} \right] \left[1 - \frac{T_2}{100} \right]$$

$$a_3 = T_4 + \text{delta} \left[\frac{T_4}{100} \right] \left[1 - \frac{T_4}{100} \right]$$

$$rzero = \frac{R_4 a_1 - R_2 a_3}{a_1 - a_3}$$

$$\text{alpha} = \frac{R_2 - R_4}{R_4 a_1 - R_2 a_3}$$

delta is the new value of DELTA computed above.

9.2.3 Compute BETA

$$x = \left[\frac{T_1}{100} \right] - 1$$

$$y = \left[\frac{T_1}{100} \right]$$

$$\text{beta} = \frac{1}{(\text{alpha})(x)(y^3)} + \frac{T_1}{(x)(y^3)} - \frac{\text{delta}}{y^2} - \frac{\frac{R_1}{r_0}}{(\text{alpha})(x)(y^3)}$$

Where T_1 and R_1 are the measured temperature and resistance at -25.00°C and alpha, rzero, and delta are the new values of ALPHA, RO, and DELTA calculated above.

Program the new values for RO (rzero), ALPHA (alpha), DELTA (delta), and BETA (beta) into the instrument with the following steps.

1. Reference Section 7.13 to display RO.
2. Press the "SET" button then use the "UP" or "DOWN" buttons until the correct numerical setting is displayed. Press the "SET" button to accept the new value.
3. Repeat step 2 for ALPHA, DELTA, and BETA.

9.2.4 Accuracy and Repeatability

Check the accuracy of the instrument at various points over the calibrated range. If the instrument does not pass specification at all set-points, repeat the Calibration Procedure.

10 Maintenance

- The instrument has been designed with the utmost care. Ease of operation and simplicity of maintenance have been a central theme in the product development. Therefore, with proper care the instrument should require very little maintenance. Avoid operating the instrument in an oily, wet, dirty, or dusty environment.
- Ice will build up on the target surface over a period of time if the unit is operated at sub-zero temperatures, allowing water to pool in the well at temperatures above 0.0°C. The user needs to drain the water build up after every use. To drain the water build up, set the instrument to a temperature above 100°C for a period of one hour causing the water to evaporate. Wipe any remaining water with a dry nonabrasive cloth.
- If the outside of the instrument becomes soiled, it may be wiped clean with a damp cloth and mild detergent. DO NOT use harsh chemicals on the surface, which may damage the paint or target.
- It is important to keep the well and target surface of the instrument clean and clear of any foreign matter.
- The instrument should be handled with care. Avoid knocking or dropping the instrument.
- If a hazardous material is split on or inside the equipment, the user is responsible for taking the appropriate decontamination steps as outlined by the national safety council with respect to the material.
- If the mains supply cord becomes damaged, replace it with a cord with the appropriate gauge wire for the current of the unit. If there are any questions, call an Authorized Fluke Hart Scientific Service Center (see Section 1.3) for more information.
- Before using any cleaning or decontamination method except those recommended by Fluke Hart Scientific, users should check with an Authorized Fluke Hart Scientific Service Center (see Section 1.3) to be sure that the proposed method does not damage the equipment.
- If the instrument is used in a manner not in accordance with the equipment design, the operation of the unit may be impaired or safety hazards may arise.

11 Troubleshooting

This section contains information on troubleshooting, CE Comments, and a wiring diagram.

11.1 Troubleshooting Problems, Possible Causes, and Solutions

In the event that the instrument appears to function abnormally, this section may help to find and solve the problem. Several possible problem conditions are described along with likely causes and solutions. If a problem arises, please read this section carefully and attempt to understand and solve the problem. If the problem cannot otherwise be solved, contact an Authorized Fluke Hart Scientific Service Center (see Section 1.3). Be sure to have the model number and serial number of your instrument available.

Problem	Possible Causes and Solutions
Incorrect temperature reading	<p>Incorrect RO, ALPHA, DELTA, and BETA parameters. Find the value for RO, ALPHA, DELTA, and BETA on the Report of Calibration that was shipped with the instrument. Reprogram the parameters into the instrument (see Section 7.13, Calibration Parameters). Allow the instrument to stabilize and verify the accuracy of the temperature reading.</p> <p>Controller locked up. The controller may have locked up due to a power surge or other aberration. Initialize the system by performing the Factory Reset Sequence.</p> <p>Factory Reset Sequence. Hold the SET and EXIT buttons down at the same time while powering up the instrument. The instrument displays shows '-init-', the model number, and the firmware version. Each of the controller parameters and calibration constants must be reprogrammed. The values can be found on the Report of Test that was shipped with the instrument.</p>
Blank display after mains power applied	<p>Blown fuse. A fuse may have blown due to a power surge or failure of a component. Replace the fuse once. If the fuse blows a second time, it is likely caused by the failure of a component. Always replace the fuse with one of the same rating, voltage, and type. Never replace the fuse with one of a higher current rating.</p>
The Instrument heats or cools too quickly or too slowly	<p>Incorrect scan and scan rate settings. The scan and scan rate settings may be set to unwanted values. Check the Scan and Scan Rate settings. The scan may be off (if the unit seems to be responding too quickly). The scan may be on with the Scan Rate set low (if unit seems to be responding too slowly).</p>

Problem	Possible Causes and Solutions
<p>The display shows any of the following: <i>Err 1</i>, <i>Err 2</i>, <i>Err 3</i>, <i>Err 4</i>, <i>Err 5</i>, <i>Err 6</i>, or <i>Err 7</i></p>	<p>Controller problem. The error messages signify the following problems with the controller.</p> <p><i>Err 1</i> - a RAM error <i>Err 2</i> - a NVRAM error <i>Err 3</i> - a Structure error <i>Err 4</i> - an ADC setup error <i>Err 5</i> - an ADC ready error <i>Err 6</i> - a defective control sensor <i>Err 7</i> - a heater error</p> <p>Initialize the system by performing the Factory Reset Sequence describe above.</p>
<p>Temperature cannot be set above a certain point</p>	<p>Incorrect High Limit parameter. The High Limit parameter may be set below 150°C. Check this value as described in Section 7.11, Operating Parameters.</p>
<p>Ice buildup</p>	<p>At temperatures below 5°C, use the target cover and/or a gas purge. When taking measurements using the target cover, place the target cover in place and set the set-point to the desired temperature, remove the target cover, take a sample, and replace the cover. When ice forms on the target, change the set-point higher than 5°C to melt the excess ice. When the ice melts pat the excess water off with a clean dry cloth. Do not wipe the front plate. If a clean dry cloth is not available, change the set-point to 100°C or higher, to evaporate the excess water.</p> <p>Use a dry gas purge. When using a dry gas purge, the instrument will not reach minimum temperature. An example of a dry gas purge is dry nitrogen connected through a 1/8" inner diameter tube to the purge fitting located at the front bottom of the target. The nitrogen gas is controlled to fill the chamber in front of the target at a rate that will not allow airflow to affect the target. Note: If the gas contains any moisture, ice will form on the target.</p>

Problem	Possible Causes and Solutions
The IR probe does not read what the IR heat source indicates	<p>Emissivity is not the same as the IR probe and target. Adjust the IR gun or use a look up table from the IR probe manufacturer.</p> <p>Ice is on the target. Heat the unit above 5°C and remove the water.</p> <p>Ambient light may change the reading of the IR probe. Get closer to the target. A channeling tube may remove some external environmental factors.</p> <p>The laser indicator (red dot) is not the actual surface center of the IR probe (field of measurement). Check the proper use of the instrument in the IR probe manual. The field of measurement changes with distance.</p> <p>There is a difference between the display temperature and the IR heat source target (temperature gradient). The closer to ambient the target is, the lower the error will be. See Figure 1, Temperature Gradient Between Reference Probe and target Surface.</p> <p>IR probe is reading incorrectly (optic problems) or may be within its given specifications (1-10°C). Check the heat source with a known good IR probe.</p> <p>IR heat source is out of calibration. Use an external reference.</p>

11.2 Comments

11.2.1 EMC Directive

Fluke Hart Scientifics' equipment has been tested to meet the European Electromagnetic Compatibility Directive (EMC Directive, 89/336/EEC). The Declaration of Conformity for your instrument lists the specific standards to which the unit was tested.

11.2.2 Low Voltage Directive (Safety)

In order to comply with the European Low Voltage Directive (73/23/EEC), Fluke Hart Scientific equipment has been designed to meet the IEC 1010-1 (EN 61010-1) and the IEC 1010-2-010 (EN 61010-2-010) standards.